


Details	Information
Name of the Mine	Hutti Gold Mine
Owner of the Mine	M/s Hutti Gold Mines Company Limited
Date and time of accident	On 06.05.2019 at about 02:00 hrs (3 rd shift of 05.05.19)
Number of Persons killed	Nil
Number of persons seriously injured	01 (One)
Photographs (maximum 02 numbers)	 <p data-bbox="756 913 1406 1234"> Picture 01: Picture 02 Picture 02: The rear right wheel lifted and thereafter the complete machine tilted towards the left hand side. The operator who was standing on its left hand side was caught in between the pillar side and the machine. </p>
Prima facie cause of the accident	<p data-bbox="756 1267 1406 1937"> While a pneumatically operated track mounted Rocker Shovel Loader, pushing the bucket for loading blasted waste rock in a drive of an underground gold mine, the lip of the bucket hit the supporting channel of the track line, the right hand side of the loader got lifted up due to the reactive force and the machine tilted towards left hand side, thereby the operator who was standing on its left hand side, caught in between the pillar side and the machine itself, inflicting serious bodily injuries </p>