

SAFETY ALERT: 40

Dhanbad, dated 20.02.2026

SUBJECT: Fatal accident occurred due to (cause) **DUE TO RUN OVER BY TRUCK** at Andhra Pradesh Granite (Midwest) Mine (Opencast Mine) of M/s Andhra Pradesh Granite (Midwest) Private Limited.

1. Name of Mine : **ANDHRA PRADESH GRANITE (MIDWEST) MINE**
2. Name of Owner : M/s Andhra Pradesh Granite (Midwest) Private Limited
District : Prakasam
State : Andhra Pradesh
3. Mineral : Granite
4. Date and time of accident : 11.11.2025 & 08:25Hrs
5. Place of accident : Haul Roads
6. Killed :

SN	NAME	DESIGNATION	AGE	EXPERIENCE
1	Yeruva Sambireddy	Supervisor	49	One Month

7. Seriously Injured : Nil
8. Brief Cause : A truck moving in the forward direction ran over Shri Sambi Reddy, Supervisor, who was walking along the haul road.
9. Sketch showing the accident :



10. Best Practices : **Segregation of Pedestrian and Vehicle Movement**
 - Provide dedicated pedestrian walkways physically separated from haul roads.
 - Restrict pedestrian movement on haul roads to absolute minimum and only when unavoidable.**Haul Road Design and Maintenance**
 - Ensure haul roads are of adequate width, well maintained, and free from potholes.

Speed Control Measures

- Enforce strict speed limits on haul roads.
- Use speed governors, GPS tracking, and speed monitoring systems.
- Install speed breakers/rumble strips at pedestrian crossing zones and near work areas.

Visibility Enhancement

- Ensure adequate illumination on haul roads, especially during night shifts.
- Provide high-visibility reflective PPE (jackets, helmets) to all supervisors and workers.
- Fit vehicles with functional headlights, tail lamps, reverse alarms, and flashing beacons

***Safety Alert**, a tool utilized by DGMS, informs the mining industry about potential safety issues and offers recommendations to prevent such incident.

DIRECTORATE GENERAL OF MINES SAFETY
125 years in the service of the Nation