ALERT

Name of the Mine	Kammaturu Iron Ore Mine
Owner of the Mine	M/s Sandur Manganese & Iron Ore Ltd
Date and time of accident	13.04.2019 at 17:50 hrs.
Number of Persons killed	01
Number of persons seriously injured	Nil
Photographs	



Deceased person lying on the berm, after lightning struck.



Damaged Shoes.

Prima facie cause of the accident

While a mining mate was supervising the movement of dump truck for unloading, at dumping yard, a thunder storm and lightning occurred and he succumbed due to the lightning injuries.

A LIGHTNING PROTECTION STUDY TO ASSESS THE RISK ASSOCIATED WITH LIGHTNING SHALL BE CONDUCTED IN ALL OPENCAST MINES, FOR PROVIDING SUITABLE LIGHTNING PROTECTION SYSTEM, TO AVOID SUCH ACCIDENTS