

| Name of the Mine                    | Vindya Underground Mine  |
|-------------------------------------|--|
| Owner of the Mine                   | M/s South Eastern Coalfields Ltd.  |
| Date and Time of Accident           | 26.11.2016, 1300 hrs   |
| Number of persons killed            | 1 (One)  |
| Number of persons seriously injured | Nil  |
| Prime facie cause of the accident   | While a driller alongwith two other persons was walking in the gallery of a belowground coal mine, coal measuring about 1.95m X 1m to 1.3m X 0.25m to 0.4m thick parted from the side and hit the driller due to which he fell down on the floor of the gallery and received internal injuries to which he succumbed in about an hour. |

TAKE TIMELY ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE