

WARNING

Name of the Mine	Mehsana Drilling Mine- Drilling Installation-Rig IPS-700-V
Name of the Owner	M/s Oil & Natural Gas Corpn. Ltd.
Date and time of accident	19.01.2017, 08.40 hours
No. of persons killed	One
Prima facie cause of the accident	While cracking drill string joint, safety line of power tong got snapped & power tong hit the victim. He fell down on derrick floor & was found unconscious/motionless. He was sent to Civil Hospital, Mehsana and was declared brought dead. Other four co-workers got minor injuries, while trying to escape out of the spot.

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE