Brief details of a Fatal accident on 06.02.2018 at East Coast Ball Clay Mine of East Coast Minerals (located in Sy. No. 109/1, Gundugolamu Village, Dwarka Tirumala Mandal, West Godavari District, Andhra Pradesh).

SI. No.	Details	
(A)	Name of the Mine	East Coast Ball Clay Mine
(B)	Owner of the mine	Shri Sunkara Veera Bhadra Prasad
(C)	Date and time of accident	06.02.2018, at about 16:00 hrs
(D)	Number of the person killed	01(One)
(E)	Number of persons serious injured	LET-HOMATSU
(E)	Dhotographs	Attached in payt page
(F)	Photographs Drime facile cause of	Attached in next page
(G)	Prime facie cause of the accident	hile a worker entered inadvertently within the swing area of the bucket of a hydraulic excavator working at the bottom of an opencast ball clay mine to extract ore, he was hit by the bucket and received serious injuries to which he succumbed almost instantaneously.