WARNING

Name of the Mine	Kuya Colliery, Dist. Dhanbad
Name of the Owner	M/s BCCL
Date & Time of the Accident	15.08.2018; 1100 Hrs
No. of persons killed	One





Prima facie cause of the Accident

While a contractual worker ascended an electric pole without effective supervision and without the use of proper Personal Protective Equipment (PPE)and safety devices, to reconnect a 3.3KV power cable to an overhead line, which got charged inadvertently due to improper implementation of shutdown procedure, received electric shock due to coming in contact with the live conductor and fell down from the top of pole of 12m height and received grievous head injuries, which proved fatal afterwards.