

Name of the Mine	Malanjkhand Copper Mine
Owner of the Mine	M/s Hindustan Copper Limited
Date and time of accident	02/04/2018 at about 17:10 Hrs
Number of persons killed	01 (One)
Number of persons seriously injured	01 (One)
Photographs	





Prime facie cause of the accident

Failure of rear drive line of tipper and defunct of parking brake.