



WARNING

The case reported in the local print media

Name of the Mine	Palukuladoddi Road Metal and Building Stone Mine (Survey No. 453 of Palukuladoddi Village, Dist: Kurnool) (Mine is not on record of DGMS)	
Owner of the Mine	Shri A. Ramkrishnudu	
Date & Time of Accident	20.07.2018 at about 08:00hrs	
Number of Persons Killed	Two (02)	
Number of Persons Seriously Injured	Three (03)	
Photographs		
Prime Facie Cause of the Accident	While four drillers were engaged in drilling of 32mm diameter holes with jack hammer pneumatic drilling machines along face of bench in an opencast road metal quarry, a tractor driver reversed compressor mounted tractor along edge of bench in an attempt to adjust length of compressed air hose, it got uncontrolled and fell down about 2.5m to 3.0m over the drillers causing multiple bodily injuries to tractor driver & crush injuries to one of driller to which both of them died almost instantaneously and serious bodily injuries to three other drillers.	