

WARNING

Name of the Mine	Rewat Dungri Range Marble Mine (Q.L.No. 23)
Name of the Owner	Shri Hazi Mukhtyar
Date and time of accident	09.01.2018
No. of Persons killed	Two



Prima Facie Cause of the accident	"While two persons were engaged in a 46m deep and almost vertical marble opencast mine to collect diesel contained being lowered through crane from hangwall side, a mass of rock from hangwall measuring 6m (Length)X2m(height)X1.5m (thick) suddenly fell down through a height of about 36m(120ft), burying them underneath its debris resulting instant death on the spot."
-----------------------------------	---

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE