

CAUTION

Name of the mine : Godavari Khani 1 & 3 Incline Mine

Owner of the Mine : M/s Singareni Collieries Co. Ltd.

Date and time of the dangerous occurrence : 06.01.2018, 16.00 hrs.

Prima facie cause of the dangerous occurrence of fire : Loose, blasted and spalled coal was allowed to remain in large quantities in the return airway where the gallery was not connected to full dimension, causing insufficient ventilation and non-dissipation of heat which resulted in the occurrence of fire in the loose coal. Fire was quenched by jet of water and normal work was resumed after 05 hours.



**TAKE APPROPRIATE ACTION(S) TO STOP
RECURRANCE OF SUCH INCIDENCE IN FUTURE**

