




**DGMS SAFETY ALERT: 13/2024**

**Dhanbad, dated 06.06.2024**

**Subject: Natural death occurred on 05.04.2024 at Sial Ghoghri (UG) coal mine of M/s. RCCPL.**

S.No	Subject	Details
1.	Name of Mine	Sial Ghoghri coal mine
2.	Name of Owner	M/s. RCCPL
	District	Chhindwara
	State	Madhya Pradesh
3.	Mineral	coal
4.	Date and time of accident	05.04.2024, at about 02:30 Hrs.
5.	Place of accident	-1DIP/42L-43L
6.	Distance from Face	1420 m
7.	Killed	One Name: Satvant Kumar Patle, Designation: Driller/ bolter (Contactor's employee), Age: 34 Years, 7 months Experience: 3 years 07 Months
6.	Seriously Injured	Nil
7.	Brief Cause	A person was deployed for the supervision of dressing, drilling, supporting, and blasting operations. The work was carried out under his supervision until 13:10 hours, after which he left the panel without informing any official. He was found lying unconscious on the ground in the traveling roadway at about 14:30 hours. He was immediately carried to the surface on a stretcher and transported to a nearby hospital, where the medical officer on duty examined him and declared him brought dead after one hour and 15 minutes.

8 Sketch showing the accident



9. Best Practices

1. Educate the persons employed in the mine on critical health issues which may likely to occur and action to be taken thereof.
2. Provide all prescribed medicines at first -aid stations and first -Aid rooms.
3. Train and retrain all the supervisors on first-aid and CPR.
4. Provide mechanism to render immediate medical assistance.
5. Provide quick evacuation in case of emergency.

**Safety Alert**, a tool utilized by DGMS, informs the mining industry about potential safety issues and offers recommendations to prevent such incidents in mines.