

# CAUTION

Name of the mine : Gorumahisani Iron Ore Mine  
Owner of the Mine : M/s Ghanashyam Misra & Sons (P) Ltd.  
Date and time of the accident : 11.05.2017 10:50 AM  
Number of persons Killed : 2 (Two)



Prima facie cause of the accident : Loaded tipper transporting iron ore crossed the berm at the turning on the left side of the haul road and toppled down causing fatal injury to two persons.

**STOP RECURRENCE OF SUCH TYPE OF ACCIDENT IN FUTURE**