

Name of the mine	Krishna Sai Granite Mine II		
Name of the Owner	M/S Krishna Sai Granites		
Date and time of the accident	18.09.2019 at about 06.30 AM		
No. of Persons killed	1		





Place over which the deceased fell from		Place from which the deceased slip and		
a height of 7.0m		fell over a lower bench.		
a height of 7.0m Prima facie cause of the accident		fell over a lower bench. While a helper of a wagon drill machine placed at the edge of a dimensional stone bench, was assisting the operator of the machine in maintenance work under the supervision of a mine Foreman, standing on the side of the bench he suddenly fell down to a depth of 7.0m in next lower bench, causing serious bodily injuries which proved fatal on the way to hospital		