

SI No.	Details	
(A)	Name of the Mine	Jhiria Underground Mine
(B)	Owner of the Mine	M/s South Eastern Coalfields Ltd.
(C)	Date and Time of Accident	17.10.2018 , 0530 hrs
(D)	Number of persons killed	1 (One)
(E)	Number of persons seriously injured	Nil
(F)	Photographs (maximums two numbers)	As the accident occurred in underground, no photographs were taken.
(G)	Prime facie cause of the accident	While a dresser was returning from face after dressing in development district of belowground coal mine working, he was run over by LHD inflicting serious bodily injuries to which he succumbed almost instantaneously.