

| SI. | Details | Information |
|-----|--|---|
| No. | | |
| 1. | Name of the Mine | Muthurayaswamy Stone Crusher (Quarry) |
| 2. | Owner of the Mine | Shri K.M. Hombe Gowda |
| 3. | Date and time of the accident | 13.03.2019 at 10:00 am |
| 4. | The number of persons killed. | One |
| 5. | The number of persons seriously injured. | One |
| 6. | Photographs (maximum two numbers) | |
| 7. | Prime facie cause of the accident. | "While two persons were drilling holes with jack-hammer on the bench of an opencast stone quarry for blasting, the drill rod penetrated into unknown misfire charge hole, which lead to explosion, causing serious bodily injury to both of them. One of them was declared brought dead by the doctors at the hospital after one hour and other person was seriously injured on his left eye, nose and left side of abdomen |

Safety is a State of Mind. Accidents are by Absence of Mind

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENTS